





**3M Australia Pty Limited** Building A, 1 Rivett Road North Ryde, NSW 2113

Phone: +61 2 9498 9333 Fax: +61 2 9498 9666 Web: 3M.com.au

Product Information: 136 136 ABN 90 000 100 096

## 3M<sup>™</sup> Scott<sup>™</sup> X380 and X190 Thermal Imager Rechargeable Battery Care and Maintenance Update

Attention: 3M Distributors.
Please forward to your end user customers immediately.

Dear valued customer,

3M Scott has updated its advice about the storage and maintenance of the rechargeable batteries in the aforementioned models (part numbers listed in the table below). This information should be used in conjunction with the advice contained in the User Instructions.

- Always inspect batteries before use.
- Ensure the battery is clean and dry prior to installing the battery into the camera or charger.
- To ensure long service life, it is recommended that batteries are stored between 14°C (58°F) and 30°C (95°F)
- The batteries should always be removed from the thermal imager before storage for extended periods.
- Never try to open or service a battery pack. There are no user serviceable parts in the battery pack.

## In addition:

- We recommend batteries that are not used for extended periods be charged to at least 50% each month (two yellow LED on the battery status)
- We recommend batteries in storage be checked at least once a month for:
  - Level should be maintained at greater than 25% charge (one red LED on the battery status)
  - o Damage
  - o Corrosion or leakage
  - o Functionality including in a charger and camera

If the battery is damaged, unable to maintain charge, fails to function correctly or fails one of the above criteria, remove the battery from service for proper disposal and replacement. Dispose of depleted or damaged batteries in accordance with local environmental regulations or return them to 3M Scott for safe disposal or repair/replacement. The User instructions contain details of how to return batteries.

3M Scott requests immediate onward communication of this notice to end users. If you have any questions in relation to the above, please contact your 3M Scott technical representative or local sales representative.

## Part numbers affected:

ISG Part Numbers	Scott Part Number	3M Item Id	Item Description
	2030493	XP100147402	X380 RECHARGEABLE BATTERY
	8003029	XP100287950	X380N TIC, 2BATT, CHARG, LANYARD, CASE (LI2)
X380-2B-HC 3B	8003887	XP100292604	X380-2B-HC 3B LRG KIT VIDEO REC 2 BATTRY
X380-5A-HC 5B	8003061	XP100549268	X380-5A-HC 5B LARGE KIT VIDEO RE
X380-PAC-SC	2031589	XP100550431	X380 SA FIRE SPEC 3B SOFT CASE X380-PAC- SC X380 SAMFS KIT COLOURED BUTTONS
	8002929		X SERIES NFPA COMPLIANT BATTERY (US)
	8002965		X SERIES STANDARD BATTERY
60-0005-A5-01			X380 STANDARD RECHARGEABLE BATTERY
60-0005-A5-02	2030538		X380 NFPA COMPLIANT RECHARGEABLE BATTERY
60-0005-A5-03		XP100551272	X380 STANDARD RECHARGEABLE BATTERY

The 3M Scott Fire & Safety team of sales and technical service professionals are committed to providing you with superior quality, value, and service and stand ready to assist you with any questions relating to this notice.

Thank you for your continued support of 3M Scott products.

Kind regards

## Sanya Kranenburg

PAPR/Airline/Escape/SCBA/TIC/Welding Portfolio Manager - ANZ 3M Personal Safety Division
Building A 1 Rivett Road, North Ryde 2113 Australia
Mobile: + 61 (0) 467 779 750
<a href="mailto:skranenburg@mmm.com">skranenburg@mmm.com</a>